

Fregatweg 42 6222NZ Maastricht
Monday to Friday (+31) 043-3688 444
Feijen 07:00 tot 17:00 - Multisteel 06:00 tot 17:00

Emergency 24/7 +31 043-3688 555/556



English



Read and sign the document.

Then report to the shipper in the hall.

- **Respect:** Everyone is treated with respect!
- **Safety:** Don't create any unsafe situations.
- **Trailer entry:** Only enter using the available staircase, and do not enter the trailer during loading.
- **Usage of crane:** It is strictly forbidden for drivers to handle cranes.
- **Axis distribution:** The driver is responsible for correct axle distribution.
- **Lashing:** Secure the goods safely while following the correct Load Restraint Guideline (LRG/TAD).

Always follow the safety instructions of the shipper!

If these rules are not followed, the shipment will be refused.

Checklist:	Yes	No	Amount
PPE's: helmet, shoes, long pants and shirt with long sleeves?			
Trailer: in good condition, and the roof opens without any issues?			
Trailer: the trailer is empty upon arrival?			
Materials: Towing bar present?			
Materials: anti slipping mats (8mm thick) available? Slipping mats given?			
Materials: sufficient straps + corners available?			


Read and complied with, sign this document before loading and return it to the weighbridge staff.
By signing, the driver agrees that Feijen's or Multisteel's guidelines have been followed.

Truck number _____
Shipment nr. _____


Signature _____

See the other side of this paper for the collection plan/ loading instructions.

Feijen:



Multisteel:



Z.O.Z.

[illegible]

1. PARK YOUR TRUCK at the gate



3. OPEN YO

4. CLEAR THE TRAILER



5. LOADING BY CRANE / FORKLIFT



A photograph showing a red SIO RT HOME truck parked in a warehouse. A yellow crane is mounted on the truck, lifting a large blue barrel. The warehouse floor is marked with red and white stripes. In the background, there are stacks of goods and a yellow forklift.

6. FOLLOW LOAD RULE

COILSTRAPPING

Direction

100 - 450 mm
See Table 7

500 mm

100 mm

RESTRAINT GUIDELINE

PLATE STRAPPING

Always make a head strapping!

Always make a head strapping!

8. WEIGHBRIDGE



A black silhouette of a truck is shown on a black horizontal line representing a weighbridge. Below the line is a black triangle representing the fulcrum.

9. CMR from SCM

